


Assembly Instructions





Page 8: Please remove and discard using a flat head screwdriver the existing parts #RC3 + RA1 as illustrated.




Contents


586	काञ्चा कर कर मा प्रदेश का अवाह		1	
989	→		1	
991			1	
992			2	
7603			1	
7604			1	
7605			1	
7606			1	
465	M4x8mm		8	
422			8	
411			2	
466			2	
4008			4	
7441	S. Contraction of the contractio		1	





Contents

7607		2	
22		1	
7220		1	
99		1	
RC3		1	
RA1		1	
SF		1	











Item		Qty.	
989	>	1	
991		1	
4008		4	
411		2	b 989
	b	991	a+b
a 991	411	b 4008	




Item		Qty.	
7604		1	
	370		1/4" 7 mm
7605		1	
7606		1	
		,	
465		2	
	M4x8mm		
422		2	7605
	M4		
	7604		7606
a	504		422




Item	Qty.
7607	2
465	2
422	2










Item	Qty.
7603	1
465	4
422	4












6			
Item win	Qty. 1		
	a b		
a		b	




- **EN** Window Location
- **DE** Fenster Standort
- FR Fenêtre Emplacement
- ES Ventana Ubicación








































ltem	Qty.
RA1	1























Item Window	Qty. 1	
		a -
a		









28 July 2014 11:37 AM